

**From:** Ex. 4 - CBI  
**Sent:** 1/25/2012 10:00:35 AM

**To:** "Richard Rupert/R3/USEPA/US" <Rupert.Richard@epamail.epa.gov>  
**CC:**  
**Subject:** Re: EPA Sampling

Moody will have sufficient personel onsite to implement today. We'll discuss when this afternoon

Ex. 4 - CBI

Senior Geologic Technician  
Moody & Associates  
685 Broad St Extension  
Suite 1  
Waverly, NY 14892

**Ex. 4 - CBI**

Sent from my iPhone

On Jan 25, 2012, at 9:53, "Richard Rupert" <Rupert.Richard@epamail.epa.gov> wrote:

Just one clarification, I am not saying we should necessarily use this procedure today since some of us may not have enough staff to accomplish. I would though like to try it to see how well it works. We can still use the old method until sufficient staff support is available.  
(Thanks Denis for sending this email out for me.)

Richard Rupert  
On-Scene Coordinator  
Region III U.S.Environmental Protection Agency  
1650 Arch Street, 3HS31  
Philadelphia, PA 19103-2029  
(215) 814-3463 FAX (215) 814-3254  
e-mail <mailto:rupert.richard@epa.gov> [rupert.richard@epa.gov](mailto:rupert.richard@epa.gov)

**From:** Ex. 4 - CBI

**Sent:** 01/25/2012 02:36 PM GMT

**To:** John Smelko <[john.smelko@cabotog.com](mailto:john.smelko@cabotog.com)>; Andy Mehalko <[andy.mehalko@cabotog.com](mailto:andy.mehalko@cabotog.com)>; "Brokenshire, Stephen" <[sbrokenshi@pa.gov](mailto:sbrokenshi@pa.gov)>

**Cc:** Richard Rupert Ex. 4 - CBI

**Subject:** EPA Sampling

All,

Rupert and I were discussing ways to speed up the sampling process this morning in preparation of collecting split samples at the [redacted] property this afternoon. Rupert's suggestion was that after the purge and parameter stabilization has been completed from the wellhead, the samples are collected simultaneously from the wellhead and the kitchen faucet.

I agree that this will reduce time on site and I do not see any technical issues with this approach. I already spoke with John and Andy of Cabot and they are on board with this approach. If anyone has any issues with this or suggestions please let Rupert know.

Ex. 4 - CBI

Senior Geologic Technician

cid:image001.jpg@01CBD9B6.032FCA50

Moody & Associates, Inc.  
685 Broad Street Extension  
Suite 1  
Waverly, NY 14892

**Ex. 4 - CBI**

\*\*\*\*\* ATTACHMENT NOT DELIVERED \*\*\*\*\*

This Email message contained an attachment named  
image001.jpg

which may be a computer program. This attached computer program could contain a computer virus which could cause harm to EPA's computers, network, and data. The attachment has been deleted.

This was done to limit the distribution of computer viruses introduced into the EPA network. EPA is deleting all computer program attachments sent from the Internet into the agency via Email.

If the message sender is known and the attachment was legitimate, you should contact the sender and request that they rename the file name extension and resend the Email with the renamed attachment. After receiving the revised Email, containing the renamed attachment, you can rename the file extension to its correct name.

For further information, please contact the EPA Call Center at (866) 411-4EPA (4372). The TDD number is (866) 489-4900.

\*\*\*\*\* ATTACHMENT NOT DELIVERED \*\*\*\*\*

\*\*\*\*\* ATTACHMENT NOT DELIVERED \*\*\*\*\*

This Email message contained an attachment named  
image001.jpg

which may be a computer program. This attached computer program could contain a computer virus which could cause harm to EPA's computers, network, and data. The attachment has been deleted.

This was done to limit the distribution of computer viruses introduced into the EPA network. EPA is deleting all computer program attachments sent from the Internet into the agency via Email.

If the message sender is known and the attachment was legitimate, you should contact the sender and request that they rename the file name extension and resend the Email with the renamed attachment. After receiving the revised Email, containing the renamed attachment, you can rename the file extension to its correct name.

For further information, please contact the EPA Call Center at (866) 411-4EPA (4372). The TDD number is (866) 489-4900.

\*\*\*\*\* ATTACHMENT NOT DELIVERED \*\*\*\*\*

\*\*\*\*\* ATTACHMENT NOT DELIVERED \*\*\*\*\*

This Email message contained an attachment named  
image001.jpg

which may be a computer program. This attached computer program could contain a computer virus which could cause harm to EPA's computers, network, and data. The attachment has been deleted.

This was done to limit the distribution of computer viruses introduced into the EPA network. EPA is deleting all computer program attachments sent from the Internet into the agency via Email.

If the message sender is known and the attachment was legitimate, you should contact the sender and request that they rename the file name extension and resend the Email with the renamed attachment. After receiving the revised Email, containing the renamed attachment, you can rename the file extension to its correct name.

For further information, please contact the EPA Call Center at (866) 411-4EPA (4372). The TDD number is (866) 489-4900.

\*\*\*\*\* ATTACHMENT NOT DELIVERED \*\*\*\*\*